

Applicants: Masaoka, et al Filed: June 21, 2001 For: ASSEMBLY OF A PNEUMATIC TIRE... Attorney Docket No. Q62630

1/23


[Fig.1]






2/23

[Fig.2]




The state of the s

[Fig.3]




4/23


[Fig.4]




[Fig.5]



[Fig.6]






Bending deformation $is\ small$

Attorney Docket No. Q62630

[Fig.7]



Applicants: Masaoka, et al


Filed: June 21, 2001

For: ASSEMBLY OF A PNEUMATIC TIRE...

Attorney Docket No. Q62630

8/23

[Fig.8]



Ground contact length L0 when eccentricity is zero

$$(\text{eccentricity}) = \frac{L0-L1}{L0}$$

Actual ground contact length L1 is smaller than L0 (when eccentricity is zero) because of eccentricity.

Applicants: Masaoka, et al Filed: June 21, 2001


For: ASSEMBLY OF A PNEUMATIC TIRE...

Attorney Docket No. Q62630

9/23


[Fig.9]


The property of the property o



Attorney Docket No. Q62630

[Fig.10]






12/23

[Fig.12]


I THE DESIGNATION OF THE WAS A SECOND TO SECOND THE SECOND OF THE SECOND



S D

Attorney Docket No. Q62630

[Fig.13]




Applicants: Masaoka, et al Filed: June 21, 2001

For: ASSEMBLY OF A PNEUMATIC TIRE...


Attorney Docket No. Q62630

[Fig.14]




Attorney Docket No. Q62630

[Fig.15]




[Fig.16]



Attorney Docket No. Q62630

[Fig.17]




Applicants: Masaoka, et al Filed: June 21, 2001

For: ASSEMBLY OF A PNEUMATIC TIRE...


Attorney Docket No. Q62630

[Fig.18]




Attorney Docket No. Q62630


19/23



[Fig.20]




[Fig.21]



Attorney Docket No. Q62630

22/23

[Fig. 22]



Applicants: Masaoka, et al Filed: June 21, 2001

For: ASSEMBLY OF A PNEUMATIC TIRE... Attorney Docket No. Q62630

23/23

[Fig.23]

